

**Illinois Commerce Commission**  
**Pipeline Safety**  
**Pipeline Safety Report**

<b>Operator: AMEREN ILLINOIS COMPANY</b>	<b>Operator ID#: 32513</b>
<b>Exit Meeting Contact: Dwayne Wells</b>	<b>Total Man Days: 2</b>
<b>Pipeline Safety Representative(s): Donald Hankins</b>	
<b>Company Representative to Receive Report: Michael Fuller</b>	<b><u>Emailed Date:</u></b>
<b>Company Representative's Email Address: mfuller2@ameren.com</b>	08/13/2014

**Inspection Summary**

<b>Inspection Type</b>	<b>Location</b>	<b>ICC Analyst</b>	<b>Inspection Unit(s)</b>	<b>Man Day(s)</b>	<b>Inspection Date(s)</b>	<b>Contact(s)</b>
Design Testing and Construction	Jerseyville	Donald Hankins	Jerseyville/Virden	2	7/1/2014, 7/2/2014	Dwayne Wells, John Sigler

**Statement of Activities**

On July 1-2, 2014, a construction audit was conducted at Ameren Illinois, in Jerseyville, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

A new PE plastic gas main was installed at Country Road & Dolen Lane in Jerseyville, Illinois. On July 1, 2014, an Ameren crew was installing a 2-inch PE main. The crew trenched in 480 feet of pipe, at a depth of 3 feet.

On July 2, 2014, the Ameren crew directional bored in 220 feet of PE pipe. The two sections of pipe were connected by using a 2-inch electro fusion fitting. This pipe was to be pressure tested at a later date.

**INSPECTION FINDINGS**

**Design Testing and Construction**

**Issues(s) Found:**

**[NO ISSUES FOUND]**

**Notice Of Amendment(s) Found:**

**[NO NOAS FOUND]**

**Notice Of Violation(s) Found:**

**[NO NOPVS FOUND]**

**PAST INSPECTION FINDINGS**

**Issue(s) Corrected:**

**[NO ISSUES CORRECTED]**

**Notice Of Amendment(s) Corrected:**

**[NO NOAS CORRECTED]**

**Illinois Commerce Commission**  
**Pipeline Safety**  
**Pipeline Safety Report**

**Notice of Violations(s) Corrected:**

**[NO NOPVS CORRECTED]**